

SCANDIAG

Packing List										
NO.	Item	Description	Qty		NO.	Item	Description	Qty		
1	BODY	BODY	1		17	ADAPTER	CITROEN-2	1		
2		BLUETOOTH ADAPTER	1		18		DAZHATSU-4	1		
3	ADAPTER	BMW-20	1		19		FIAT-3	1		
4		BENZ38	1		20		MI TSUBI SHI HYUNDAZ-12+16	1		
5		CHRYSLER-6	1		21		NI SSAN-3	1		
6		DAEWOO-12	1		22		SUZUKI -3	1		
7		FORD-6+1	1		23		SSANGYONG-14	1		
8		GM/VAZ-12	1		24		Uni versal -3	1		
9		HONDA-3	1		25		USB cable	1		
10		ADAPTER	KIA-17	1			26	CABLE	OBD 16pin female-16pin male	1
11			MAZDA-17	1			27		DB 9pin female-9pin female	1
12			SUBARU-9	1			28		DB 15pin female-15pin female	1
13			SSANGYONG-20	1			29		DB 15pin female-OBD 16pin female	1
14			TOYOTA-22	1			30		DB 15pin female-OBD 16pin male	1
15			TOYOTA-17	1			31	ACCESSORY	USER MANUAL	1
16			AUDI -2+2	1						
17			BENZ-16	1						

HongSheng Electronic Technology HK Limited.

ADD: No. 2401, Meilongyuan, Longhua Town, Meilong Street, Baoan District, Shenzhen, Guangdong Province

Tel: 86-755-84419345 www.scandiag.com

SCANDIAG

Software List								
No.	Brand	Language	No.	Brand	Language	No.	Brand	Language
1	ACURA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	18	JP ISUZU	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	35	SMART	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
2	AUDI	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	19	KIA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	36	SPRINTER	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
3	BENZ	ENG <input type="checkbox"/>	20	LANCIA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	37	SSANGYONG	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
4	BMW	ENG <input type="checkbox"/>	21	LANDROVER	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	38	SUBARU	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
5	CHRYSLER	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	22	LEXUS	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	39	SUZUKI	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
6	CITROEN	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	23	MAZDA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	40	TOYOTA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
7	DACIA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	24	MI TSUBISHI	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	41	UAS FORD	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
8	DAEWOO	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	25	NI SSAN	ENG <input type="checkbox"/>	42	VAUXHALL	ENG <input type="checkbox"/> SPAN <input type="checkbox"/>
9	DAI HATSU	ENG <input type="checkbox"/> PORTU <input type="checkbox"/>	26	OPEL	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	43	VOLVO	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
10	EODB2	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	27	PEUGEOT	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	44	VW	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>
11	EURO FORD	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	28	PORSCHE	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			
12	FIAT	ENG <input type="checkbox"/>	29	RENAULT	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			
13	GM	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	30	ROMEO	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			
14	HONDA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/>	31	ROVER	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			
15	HYUNDAI	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	32	SAAB	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			
16	INFINITI	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	33	SEAT	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			
17	JAGUAR	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>	34	SKODA	ENG <input type="checkbox"/> SPAN <input type="checkbox"/> PORTU <input type="checkbox"/>			

HongSheng Electronic Technology HK Limited.

ADD: No. 2401, Meilongyuan, Longhua Town, Meilong Street, Baoan District, Shenzhen, Guangdong Province

Tel: 86-755-84419345 www.scandiag.com